

Hunter Street West



Summary of Existing Conditions

The former Church yard is not properly accessible. There are a number of trees and shrubs that require care and/or replacement. There are also areas of the church yard that are concealed from the street which contributes to an uninviting outdoor space. At night time, there are areas that are not well lit which, for many, can contribute to poor security and diminished sense of personal safety. The overall quality of the site furniture is not adequate, benches are placed too close and without good visibility to the street.

There are a few trees and flowering shrubs that are in good condition and that provide shade and visual interest.

This panel demonstrates the current condition of the site, and points to some of the major issues that will be addressed by the renovation.

Graphic Legend

- Pedestrian Entrance
- Existing Pedestrian path
- Potential Pedestrian path
- Physical barrier
- Existing bench
- Vehicular access
- Area of Concern
- Existing tree to be preserved/relocated
- Insufficient pedestrian lighting
- Lack of signage and wayfinding

