wood.

Appendix F

Data Gaps

Summary of Noted Storm Sewer Data Gaps in Beach Boulevard Community (November 23, 2021)

- Missing length: Length is not available for all pipes. Differences have been noted between the GIS measured pipe length and the database specified pipe length.
- Missing pipe size and length on pipes under the QEW at Bayside Avenue



• Various missing elevations, many of which cross the Q.E.W. or are located on the south-west side of the Q.E.W.



• Reversed slopes near north end cul-de-sac at Beach Boulevard



• Pipe placement inconsistencies at Pipe 55427 in 2021-01 data and 2021-05 data



• Grafton pump station has no outlet in the database. Outfall HZ03OF02 has no pipe connection.



Abnormal conveyance profiles in addition to reversed slopes in various locations.
One example is presented below.

