



Hamilton

PLACES OF WORSHIP INVENTORY FORM

New Apostolic Church

Address: 323 Hatt St

Community: Dundas

Heritage Status: Inventoried

Construction Date: 1955

Architectural Style / Influence:



Inventory Update and Preliminary Evaluation:

Property Use (Observed): Adaptive Reuse

Design Integrity: Compromised

Classification: Inventory Property

Recommendation: No Action Required

Preliminary Design/Physical Value:

None identified.

Preliminary Historical/Associative Value:

The property is associated with the New Apostolic Church of Canada.

Preliminary Contextual Value:

None identified.

IRWG Review Date: 11/9/2020



Hamilton

PLACES OF WORSHIP INVENTORY FORM

Former Place of Worship (Crodon Kitchen & Bath Centre)

Address: 69 King St E

Community: Dundas

Heritage Status: Inventoried

Construction Date: 1951

Architectural Style / Influence: Contemporary



Inventory Update and Preliminary Evaluation:

Property Use (Observed): Adaptive Reuse

Design Integrity: Modified

Classification: Inventory Property

Recommendation: No Action Required

Preliminary Design/Physical Value:

The property is representative example of the vernacular architectural style.

Preliminary Historical/Associative Value:

The property was historically affiliated with the Pentacostal church.

Preliminary Contextual Value:

The property is important in supporting the character of the area.

IRWG Review Date: 11/9/2020



Hamilton

PLACES OF WORSHIP INVENTORY FORM

Christian Life Assembly

Address: 165 King St W

Community: Dundas

Heritage Status: Inventoried

Construction Date: 1837

Architectural Style / Influence:



Inventory Update and Preliminary Evaluation:

Property Use (Observed): Place of Worship

Design Integrity: Compromised

Classification: Character-Supporting Resource

Recommendation: Include in Register (Non-designated)

Preliminary Design/Physical Value:

The property is an example of vernacular architecture.

Preliminary Historical/Associative Value:

The property has direct associations with a potentially significant belief and institution as the first Presbyterian Church in Dundas. The property is associated with the Pentacostal faith.

Preliminary Contextual Value:

The property is important in supporting the character of the area.

IRWG Review Date: 12/7/2020



Hamilton

PLACES OF WORSHIP INVENTORY FORM

Former Place of Worship (Royal Canadian Legion)

Address: 276 King St W

Community: Dundas

Heritage Status: Inventoried

Construction Date: 1846

Architectural Style / Influence: Georgian



Inventory Update and Preliminary Evaluation:

Property Use (Observed): Adaptive Reuse

Design Integrity: Compromised

Classification: Character-Supporting Resource

Recommendation: Include in Register (Non-designated)

Preliminary Design/Physical Value:

The original portion of the church is representative of the vernacular style of architecture.

Preliminary Historical/Associative Value:

The property has historic associations with the Methodist and Presbyterian churches. The property has direct associations with a potential significant belief as the forerunner of the Presbyterian Church established 1861.

Preliminary Contextual Value:

None identified.

IRWG Review Date: 12/7/2020



Hamilton

PLACES OF WORSHIP INVENTORY FORM

St. Mark's United Church

Address: 1 Lyndale Dr

Community: Dundas

Heritage Status: Inventoried

Construction Date: 1961

Architectural Style / Influence: Contemporary



Inventory Update and Preliminary Evaluation:

Property Use (Observed): Place of Worship

Design Integrity: Preserved - Intact

Classification: Character-Defining Resource

Recommendation: Include in Register (Non-designated)

Preliminary Design/Physical Value:

The property is representative example of the Modern / Contemporary architectural style.

Preliminary Historical/Associative Value:

The property is affiliated with the United Church. The property demonstrates or reflects the work or ideas of a potentially significant architect (James Albert Murray, Toronto).

Preliminary Contextual Value:

The property is important in maintaining the character of the area. The property is visually and historically linked to its surroundings. The property may be considered to be a local landmark.

IRWG Review Date: 11/23/2020



Hamilton

PLACES OF WORSHIP INVENTORY FORM

Knox Presbyterian Church

Address: 23 Melville St

Community: Dundas

Heritage Status: Designated

Construction Date: 1874

Architectural Style / Influence: Gothic Revival



Inventory Update and Preliminary Evaluation:

Property Use (Observed): Place of Worship

Design Integrity: Preserved - Intact

Classification: Significant Built Resource

Recommendation: No Action Required

Preliminary Design/Physical Value:

See Cross-Melville Heritage Conservation District Plan.

Preliminary Historical/Associative Value:

See Cross-Melville Heritage Conservation District Plan.

Preliminary Contextual Value:

See Cross-Melville Heritage Conservation District Plan.

IRWG Review Date:



Hamilton

PLACES OF WORSHIP INVENTORY FORM

St. James' Anglican Church

Address: 137 Melville St

Community: Dundas

Heritage Status: Inventoried

Construction Date: 1926

Architectural Style / Influence: Neo-Gothic



Inventory Update and Preliminary Evaluation:

Property Use (Observed): Place of Worship

Design Integrity: Modified

Classification: Character-Supporting Resource

Recommendation: Include in Register (Non-designated)

Preliminary Design/Physical Value:

The property is representative example of the Neo-Gothic architectural style. The property displays a high degree of craftsmanship and artistic merit.

Preliminary Historical/Associative Value:

The property is affiliated with the Anglican Church. The property has direct associations with potentially significant belief as the only Anglican church still standing in Dundas. The property demonstrates or reflects the work or ideas of a potentially s

Preliminary Contextual Value:

The property is important in maintaining the character of the area. The property is visually and historically linked to its surroundings. The property may be considered to be a local landmark.

IRWG Review Date: 11/9/2020



Hamilton

PLACES OF WORSHIP INVENTORY FORM

St. Paul's United Church


Address: 29 Park St W

Community: Dundas

Heritage Status: Designated

Construction Date: 1933

Architectural Style / Influence: Gothic



Inventory Update and Preliminary Evaluation:

Property Use (Observed): Place of Worship

Design Integrity: Preserved - Intact

Classification: Significant Built Resource

Recommendation: No Action Required

Preliminary Design/Physical Value:

See Cross-Melville Heritage Conservation District.

Preliminary Historical/Associative Value:

See Cross-Melville Heritage Conservation District.

Preliminary Contextual Value:

See Cross-Melville Heritage Conservation District.

IRWG Review Date:



Hamilton

PLACES OF WORSHIP INVENTORY FORM

Former Place of Worship (Dundas Valley Montessori School)

Address: 108 Park St W

Community: Dundas

Heritage Status: Inventoried

Construction Date: 1866

Architectural Style / Influence:



Inventory Update and Preliminary Evaluation:

Property Use (Observed): Adaptive Reuse

Design Integrity: Modified

Classification: Character-Supporting Resource

Recommendation: Include in Register (Non-designated)

Preliminary Design/Physical Value:

The property is a representative example of the Classical Revival architectural style.

Preliminary Historical/Associative Value:

The property has direct associations with a potentially significant belief and institution. The property is comprised of the first building that was purpose-built to house the Dundas Baptist congregation.

Preliminary Contextual Value:

The property is important in maintaining the character of the area. The property is visually and historically linked to its surroundings.

IRWG Review Date: 12/7/2020



Hamilton

PLACES OF WORSHIP INVENTORY FORM

St. Augustine's Catholic Church

Address: 54 Sydenham St

Community: Dundas

Heritage Status: Designated

Construction Date: 1863

Architectural Style / Influence: Gothic Revival



Inventory Update and Preliminary Evaluation:

Property Use (Observed): Place of Worship

Design Integrity: Preserved - Intact

Classification: Significant Built Resource

Recommendation: No Action Required

Preliminary Design/Physical Value:

See designation By-law Number 3899-90.

Preliminary Historical/Associative Value:

See designation By-law Number 3899-90.

Preliminary Contextual Value:

See designation By-law Number 3899-90.

IRWG Review Date: