

## Voting Place Inspection Checklist

Tiammon			V	Vard: 8		Poll: 3	
□ Regular Poll ☑	□ Institu	utional Poll		□ Con	nmuni	ty Poll	
Completed by: Dave Michal		Date: Ju	uly 10 & Ju	lly 25			
Section 1: Building Inform	ation						
Building Name	Dave Andreych	nuk Arena –	(905) 546-	3747			
Building Address	25 Hester Stree	et, L9A 2N3					
Section 3: Building Exterio	or						
	S	ignage					
Does the location have signs for the	ne street	□ Yes 🗹		Notes:			
address and/or building name that	are clearly	□ No					
visible from the street and well-lit	during						
evening events?							
Is the main entrance easy to find v	vhen entering	□ Yes 🗹		Notes:			
the site?		□ No					
	P	Parking					
Ques	tion		Ye	s No		Notes	
1) Is Parking available onsite? N	lote # of spaces		Ø			200+	
2) Is the parking lot paved?			Ø				
3) Parking lot general condition of	bservation? No	te: poor,		L	I		
average, good					Go	ood	
4) Are Accessibility parking space	es available (ide	entified with	Ø				
accessible parking signage)?							
Note # of spaces							
5) Are the accessible parking spa	aces located as	close as	Ø				
possible to the main entrance	?						
6) Do sidewalks have curb cuts a		parking and					-
along the route to the accessil							
7) Is on-street parking available?			Z				
8) Is on-street accessible parking	available?			Ø			

9)	Is the location accessible by DARTS?	<b>☑</b>		
10)	Is there an area for passenger drop-off/pick-up?	Ø		
11)	Is the location on a bus route?	Ø		300m from Upper
				James bus stops
12)	Is there a place to securely store bicycles?	Ø		
	Access to the Building			
	Question	Yes	No	Notes
1)	Do sidewalks, walkways, pathways to the main entrance	V		
	surfaces appear firm, stable, slip resistant?			
2)	Sidewalks, walkways, pathways to the main entrance general	Ø		
	condition observation? Note: poor, average, good			Good
3)	Are there sudden level, or slope changes to the main		Ø	
	entrance?			
4)	Is there an accessible route of travel from the parking lot to	Ø		
	the main entrance?			
5)	Accessible route of travel from the parking lot to the main	V		
	entrance general condition observation?			Good
	Note: poor, average, good			
6)	Do sidewalks, walkways, pathways appear appropriate	Ø		
	widths? (allowing two persons to pass each other easily)			
7)	Are there low hanging signs or other impediments restricting		V	
	accessible access to the building?			
8)	Are there stairs leading to the main entrance?		☑	
	If present,			
	- Surface appear firm, stable, slip resistant			
	- Uniform risers and runs (steps)			
	- Have tactile walking surface indicators at the top of flight			
	- High tonal contrast strip on leading edge of stairs			
	- Handrails on both sides			
9)	Stairs general condition observation?		n/a	
	Note: poor, average, good			
10)	Is there an accessible ramp leading to the main entrance?		n/a	
	If present,			
	- Surface appears firm, stable, slip resistant			
	- Running slope appears to meet 1:15 (every 1" in elevation,			
	15" in length)			

- Clear landing areas (the flat area at the top, bottom or			
turning transitions)			
- handrails on both sides			
11) Ramp general condition observation?		n/a	
Note: poor, average, good			
12) Is the main entrance equipped with automatic sliding doors?			
13) Would you consider the width of the main entrance doors to			
be (add response in note):			Wide
Narrow			
Standard			
Wide			
14) Entrance doors general condition observation?			Good
Note: poor, average, good			
15) Does the main entrance door(s) have a power or automatic			Double Door
door for entry?			
16) Is the door threshold more than ½ inch in height?		Ø	
17) Does the main entrance have an exterior canopy?		V	Small on main door
			and larger on
			accessible doors
Lighting	•		
Question	Yes	No	Notes
Is there lighting in the parking areas for the evening?	☑		
2) Is there lighting to illuminate sidewalks, walkways, pathways	☑		
to the main entrance?			
3) Is there lighting to illuminate the main entrance of this	Ø		
location?			
	I		

Se	Section 4: Building Interior				
Interior Access					
	Question	Yes	No	Notes	
1)	Does this location have more than one level?	Ø			
2)	Main entry and corridor flooring?			Firm	
	- Firm, slip resistant, produce minimal glare				
	- Carpet				
3)	Are there any stairs?	Ø			
	If present,				

	Confess anneau firm atable alle resistant	ı	I	Ι_
	- Surface appear firm, stable, slip resistant			
	- Uniform risers and runs (steps)			Ø
	- Have tactile walking surface indicators at the top of flight			x
	- High tonal contrast strip on leading edge of stairs			x
	- Handrails on both sides			☑
4)	Stairs general condition observation?	☑		Good
	Note: poor, average, good			
5)	Is there an accessible ramp(s)?			
	If present,			
	- Surface appear firm, stable, slip resistant			
	- Running slope appears to meet 1:15 (every 1" in		n/a	
	elevation, 15" in length)			
	- Clear landing areas (the flat area at the top, bottom or			
	turning transitions)			
	- Handrails on both sides			
6)	Ramp general condition observation?		n/a	
	Note: poor, average, good			
7)	Is there an elevator(s)?	<b>1</b>		
( )	If present,			
	- Door width, narrow, standard (36"), wide			
	· ,	Ø		
	Interior cab approx. 5'x5' or more	☑		
	- Illuminated buttons	<b>Z</b>		
	- Braille			
	- Audible indicators & signals			
	– handrails	Ø		
8)	Elevator general condition observation?			Good
	Note: poor, average, good			
9)	Is there an accessible route of travel from the main entrance	Ø		South Side doors will
	lot to voting location?			be accessible
10)	Would you consider the width of the interior doors/passages to			
	the voting location to be (add response in note):			
	Narrow			Wide
	Standard			
	Wide			
11)	Do any obstacles impede electors from reaching the voting			
	location? Note impediment obstacles.		☑	
	·			


If yes, will impediment obstacles be removed on election day?			
12) Is there a fire alarm system on site?	Ø		
13) Is there emergency lighting present?	Ø		
14) Is there access to public washrooms?	Ø		
15) Is there access to public accessible washroom(s)/stall(s)?	Ø		
16) Is there access to public telephone(s)?		Ø	
17) Is there access to public Wifi?	Ø		
Voting Location			
Question	Yes	No	Notes
1) Is the voting location within site of the main entrance?		Ø	
2) Is the voting location easy to find from the main entrance?	Ø		
3) General condition observation of voting location?			Good
Note: poor, average, good			
4) If tables need to be 6ft apart, how many can be placed in the			12+
room?			
5) Is the heating that will be provided a comfortable amount of	Ø		
heat for the anticipated use?			
6) Is the air conditioning that will be provided a comfortable	Ø		
amount of cooling for the anticipated use?			
7) Is there natural lighting in voting location?	Ø		

## **Location Drawing (include measurements)**

Please diagram the parking lot, the route to the main entrance, any ramps, walkways and accessible entrances, as well as the voting location and the route inside the building to that location.

140m to poll from main entrance

80m to poll via Hester St Entrance from accessible parking with elevator access to 2<sup>nd</sup> floor



## Section 5: Overall Assessment of Location and the Area

Large poll room. Obstacle is distance from main parking to poll. Accessible parking on west side of building offers shorter distance to elevator and no barriers to entry. Greeter to be placed on main and Hester entrances to direct electors.