

Voting Place Inspection Checklist

Tiaiiiittoii			,	Ward 8	:	Poll: 4		
□ Regular Poll ☑	□ Insti	tutional Poll		□ Community Poll				
Completed by: Dave Michal	uly 10 & J	uly 3	1					
Section 1: Building Inform	ation							
Building Name	Westmount Ro	ecreation Cer	ntre - 905	-546-	4932			
Building Address	35 Lynbrook D	Dr.						
Section 3: Building Exterio	or							
		Signage						
Does the location have signs for the address and/or building name that visible from the street and well-lit devening events?	are clearly	□ Yes ☑ □ No		Note	es:			
the cite?		□ Yes ☑ □ No		Note	es:			
		Parking						
Ques			Ye	es I	No	Notes		
Is Parking available onsite? N	lote # of space	S	l 🗹	7				
2) Is the parking lot paved?			Ū.	7				
Parking lot general condition observation? Note: poor, average, good				Good				
4) Are Accessibility parking space accessible parking signage)? Note # of spaces	es available (id	lentified with	<u> </u>					
5) Are the accessible parking spa possible to the main entrance?		s close as	D.	1				
6) Do sidewalks have curb cuts a	ar parking and	j <u>P</u>	7					
along the route to the accessit								
7) Is on-street parking available?			Q	7				
) Is on-street accessible parking available?					D71			

9)	Is the location accessible by DARTS?	V		Ideal DARTS clients
				voting location. Turn
				around at entrance.
10)	Is there an area for passenger drop-off/pick-up?	Ø		
11)	Is the location on a bus route?	V		Stop is 160m away at
				Mohawk Rd W
12)	Is there a place to securely store bicycles?	Ø		
	Access to the Building			
	Question	Yes	No	Notes
1)	Do sidewalks, walkways, pathways to the main entrance	Ø		
	surfaces appear firm, stable, slip resistant?			
2)	Sidewalks, walkways, pathways to the main entrance general	V		
	condition observation? Note: poor, average, good			
3)	Are there sudden level, or slope changes to the main		☑	
	entrance?			
4)	Is there an accessible route of travel from the parking lot to	Ø		
	the main entrance?			
5)	Accessible route of travel from the parking lot to the main			Good
	entrance general condition observation?			
	Note: poor, average, good			
6)	Do sidewalks, walkways, pathways appear appropriate	Ø		
	widths? (allowing two persons to pass each other easily)			
7)	Are there low hanging signs or other impediments restricting		V	
	accessible access to the building?			
8)	Are there stairs leading to the main entrance?		V	
	If present,			
	- Surface appear firm, stable, slip resistant			
	- Uniform risers and runs (steps)			
	- Have tactile walking surface indicators at the top of flight			
	- High tonal contrast strip on leading edge of stairs			
	- Handrails on both sides			
9)	Stairs general condition observation?		n/a	
	Note: poor, average, good			
10)	Is there an accessible ramp leading to the main entrance?		n/a	
	If present,			
	- Surface appears firm, stable, slip resistant			

	- Running slope appears to meet 1:15 (every 1" in elevation,			
	15" in length)			
	•			
	- Clear landing areas (the flat area at the top, bottom or			
	turning transitions)			
	- handrails on both sides			
11)	Ramp general condition observation?		n/a	
	Note: poor, average, good			
12)	Is the main entrance equipped with automatic sliding doors?	Ø		
13)	Would you consider the width of the main entrance doors to			Wide
	be (add response in note):			
	Narrow			
	Standard			
	Wide			
14)	Entrance doors general condition observation?	V		
	Note: poor, average, good			
15)	Does the main entrance door(s) have a power or automatic	Ø		
	door for entry?			
16)	Is the door threshold more than ½ inch in height?		Ø	
17)	Does the main entrance have an exterior canopy?	Ø		
	Lighting			
	Question	Yes	No	Notes
1)	Is there lighting in the parking areas for the evening?	Ø		
2)	Is there lighting to illuminate sidewalks, walkways, pathways	Ø		
	to the main entrance?			
3)	Is there lighting to illuminate the main entrance of this	V		
	location?			
		1		

Se	Section 4: Building Interior				
	Interior Access				
	Question	Yes	No	Notes	
1)	Does this location have more than one level?	Ø			
2)	Main entry and corridor flooring?			Firm	
	- Firm, slip resistant, produce minimal glare				
	- Carpet				
3)	Are there any stairs?		n/a		


	If present,			
	- Surface appear firm, stable, slip resistant			
	- Uniform risers and runs (steps)			
	- Have tactile walking surface indicators at the top of flight			
	- High tonal contrast strip on leading edge of stairs			
	- Handrails on both sides			
4)			/-	
4)	Stairs general condition observation?		n/a	
	Note: poor, average, good			
5)	Is there an accessible ramp(s)?		n/a	
	If present,			
	- Surface appear firm, stable, slip resistant			
	- Running slope appears to meet 1:15 (every 1" in			
	elevation, 15" in length)			
	- Clear landing areas (the flat area at the top, bottom or			
	turning transitions)			
	- Handrails on both sides			
6)	Ramp general condition observation?		n/a	
	Note: poor, average, good			
7)	Is there an elevator(s)?		n/a	
	If present,			
	 Door width, narrow, standard (36"), wide 			
	 Interior cab approx. 5'x5' or more 			
	 Illuminated buttons 			
	- Braille			
	 Audible indicators & signals 			
	- handrails			
8)	Elevator general condition observation?		n/a	
	Note: poor, average, good			
9)	Is there an accessible route of travel from the main entrance	Ø		
	lot to voting location?			
10)	Would you consider the width of the interior doors/passages to			Wide
	the voting location to be (add response in note):			
	Narrow			
	Standard			
	Wide			
11)	Do any obstacles impede electors from reaching the voting		Z	
,	location? Note impediment obstacles.			
	Totalion: Note imposiment obstacles.			

If yes, will impediment obstacles be removed on election day?			
12) Is there a fire alarm system on site?	☑		
13) Is there emergency lighting present?			
14) Is there access to public washrooms?			
15) Is there access to public accessible washroom(s)/stall(s)?	☑		
16) Is there access to public telephone(s)?		·	
17) Is there access to public Wifi?	☑		

	Voting Location				
	Question	Yes	No	Notes	
1)	Is the voting location within sight of the main entrance?	Ø			
2)	Is the voting location easy to find from the main entrance?	Ø			
3)	General condition observation of voting location?			Good	
	Note: poor, average, good				
4)	If tables need to be 6ft apart, how many can be placed in the			18	
	room?				
5)	Is the heating that will be provided a comfortable amount of	Ø			
	heat for the anticipated use?				
6)	Is the air conditioning that will be provided a comfortable	Ø			
	amount of cooling for the anticipated use?				
7)	Is there natural lighting in voting location?	Ø			
8)	Is there lighting in the voting location that will provide a	Ø			
	comfortable amount of illumination for the anticipated use?				

Location Drawing (include measurements)

Please diagram the parking lot, the route to the main entrance, any ramps, walkways and accessible entrances, as well as the voting location and the route inside the building to that location.



Section 5: Overall Assessment of Location and the Area

Most accessible of all ward 8 poll locations. No barriers to entry or interior.