



TECHNICAL STANDARDS
and SAFETY AUTHORITY

345 Carlingview Drive
Toronto, Ontario M9W 6N9
Toll free 1-877-682-8772
www.tssa.org

Inspection Report

Work Order # 14753859

Inspection Report # 10286033

Inspection Address: 10 MARKET ST S DUNDAS ON L9H 5G4 Canada	Reference Number(s): 76373	Inspection Completion Date: Nov 13, 2025
	Device Type: Passenger Elevator	Equipment Type: ED Elevator
Customer Name and Address: CITY OF HAMILTON 28 JAMES ST N 5TH FLOOR HAMILTON ON L8R 2K1 Canada	Task Type: ED Periodic Inspection	
	The facility/equipment is inspected in accordance with Ontario's Technical Standards & Safety Act and the appropriate regulations and codes. When an Inspector's order is issued, time limits for compliance reflect the severity of the violation and serve to avoid disruption of service.	

Inspection report delivered by email fmcpcomp@hamilton.ca

INSPECTION NOTES

Inspection Order(s) are issued pursuant to my authority under section 21. (1) of the Technical Standards and Safety Act, 2000.

Where inspection orders are issued, TSSA will perform a follow-up inspection to confirm compliance. The responsible party is expected to make all the necessary corrections within the compliance time specified.

Where safety tasks are issued, TSSA will not perform a follow-up inspection to confirm compliance. The responsible party is expected to make all the necessary corrections within the compliance time specified. Safety tasks may be subject to a TSSA audit inspection and/or the responsible party may be required to confirm compliance to obtain your authorization/license.

TSSA has completed an inspection of this device and has issued Safety Task(s). TSSA will not perform a follow-up inspection to confirm compliance. The responsible party is expected to make all the necessary corrections within the compliance time specified.

INSPECTION ORDER(S) and/or SAFETY TASK(S) ISSUED TO: CITY OF HAMILTON

EMAIL RECIPIENTS: fmcpcomp@hamilton.ca, tssa.hamilton@tkelevator.com, theo.maripu@tkelevator.com, katelyn.austriaco@hamilton.ca, anthony.bruno@hamilton.ca

No.	Safety Tasks	Issued Date	Compliance Date
1.	Post the current elevating device license in a conspicuous location in the car, or at an alternate location if permission has been sought from the director.	Nov 13, 2025	Feb 11, 2026
2.	The two-way communication means shall provide on demand to authorized personnel, information that identifies the building location and elevator number and that assistance is required.	Nov 13, 2025	Feb 11, 2026

As a not-for-profit regulatory authority, TSSA operates on a cost recovery basis.
(Note: This is not an invoice)

Putting Public Safety First



TECHNICAL STANDARDS
and SAFETY AUTHORITY

345 Carlingview Drive
Toronto, Ontario M9W 6N9
Toll free 1-877-682-8772
www.tssa.org

Inspection Report

Work Order # 14753859

Inspection Report # 10286033

 No street number is provided,		
--	-------------------------------------	--	--

This report is issued under the *Technical Standards and Safety Authority Act, 2000*, s. 17(1)

17. (1) An inspector may conduct an inspection and may, as part of that inspection, enter and inspect at any reasonable time the lands and premises where any of the things, parts of the things or classes of things to which this Act, the regulations or a Minister's order apply are used, operated, installed, made, manufactured, repaired, renovated or offered for sale for the purpose of,

- (a) ensuring compliance with this Act, the regulations or Minister's order;
- (b) ensuring that an authorization holder remains entitled to the authorization; or
- (c) determining whether a hazardous condition exists. 2006, c. 34, s. 25 (5)

Customer Signature & Position / Date:		Inspector Name: Gary Wang	Inspector Contact Number: +1 416-451-3416
Report Received By:	Customer Contact Number:	Inspector Email: gwang@tssa.org	

As a not-for-profit regulatory authority, TSSA operates on a cost recovery basis.
(Note: This is not an invoice)

Putting Public Safety First